

*****IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER*****
Monitoring Requirements Not Met for Tradewinds Village PWS 3424620

We are required to monitor your drinking water for specific contaminants on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards.

During the month of August 2025, our water system failed to collect additional samples following an E. coli & Total Coliform Positive sample within a timely manner.

What Should I do?

There is nothing you need to do at this time. You do not need to boil your water or use an alternative water supply. No adverse health effects are believed to have resulted from this failure to collect the required total coliform samples. General guidelines on ways to lessen the risk of infection by microbes are available from EPA's Safe Drinking Water Hotline at 1-800-426-4791.

What happened? What is being done?

In August 2025, routine monthly sampling at the Tradewinds Village groundwater well detected the presence of E. coli. A Boil Water Notice (BWN) was issued to the community within 24 hours of learning the results. The well was subsequently sanitized and flushed; however, the required repeat samples were not collected within the designated timeframe. Since then, all follow-up testing has shown no presence of bacteriological contaminants, and the BWN has been rescinded. Your drinking water is now confirmed to be free of bacteriological contamination and safe for consumption and use.

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (i.e., people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

This notice is being sent by:
Tradewinds Village
PWSID 3424620