							System-Owned Portion				Customer-Owned Portion			Entire Service Line	ntire Service Line Other Potential Sources of Lead			Additional Information to Assign Tap Monitoring Tiering					Lead Service Line Replacement (LSLR)	
Unique Service Line ID*	Street Number	Street Name*	City*			e (decimal Longitude (decimal	System-Owned Portion Service Line Material Classification*	If Non-Lead, Was Material Ever Previously Lead?	Service Line Installation Date	Notes	Customer-Owned Portion Service Line Material Classification*	Service Line Installation Date	Notes	Entire Service Line Material Classification (by Water System)	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	List Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-ol-Entry or Point-of-Us Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before July 1 19882	Current LCR Sampling Site?	Sample Site Selection Criteria (Site Tier)		Date of Customer- Owned LSLR
31973		Odom Drive	Sealy	77474			Non-Lead		1992		Non-Lead	1992		Non-Lead										
31964		Odom Drive	Sealy	77474			Non-Lead		Between 1989 and 2014		Non-Lead	Between 1989 and 2014		Non-Lead										
31956		Odom Drive	Sealy	77474			Non-Lead		1997		Non-Lead	1997		Non-Lead										
31961		Odom Drive	Sealy	77474			Non-Lead		Between 1989 and 2014		Non-Lead	Between 1989 and 2014		Non-Lead										
31969		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31971		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31972		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31974		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31958		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31960		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31962		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31963		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31965		Odom Drive	Sealy	77474			Non-Lead		1998		Non-Lead	1998		Non-Lead										
31977		Odom Drive	Sealy	77474			Non-Lead		1999		Non-Lead	1999		Non-Lead										
31978		Odom Drive	Sealy	77474			Non-Lead		1999		Non-Lead	1999		Non-Lead										
31967 31968		Odom Drive	Sealy	77474			Non-Lead		1999		Non-Lead	1999		Non-Lead										
31968		Odom Drive Odom Drive	Sealy Sealy	77474 77474			Non-Lead Non-Lead		1999 2000		Non-Lead	1999 2000		Non-Lead Non-Lead										
31959		Hilboldt Road	Sealy	77474			Non-Lead		2001		Non-Lead Non-Lead	2001		Non-Lead										
31979		Odom Drive	Sealy	77474			Non-Lead		2002		Non-Lead	2002		Non-Lead										
31970		Odom Drive	Sealy	77474			Non-Lead		2015		Non-Lead	2015		Non-Lead										
31975		Odom Drive	Sealy	77474			Non-Lead		2015 Between 1989 and 2014		Non-Lead	Between 1989 and 2014		Non-Lead										
31976		Odom Drive	Sealy	77474			Non-Lead		Between 1989 and 2014 Between 1989 and 2014		Non-Lead	Between 1989 and 2014 Between 1989 and 2014		Non-Lead										
31957		Odom Drive	Sealy	77474			Non-Lead		Between 1989 and 2014 Between 1989 and 2014		Non-Lead	Between 1989 and 2014 Between 1989 and 2014		Non-Lead										
31900	0.040	Course of the					Thur Public		Sectores: 1967 800 2014		HUIP LINK	Serveren 1989 and 2014		THUR PLANE.										